

CORRIGENDUM-II**NAME OF THE WORK:- Repair And Rehabilitation works of Existing structures For Fact Cochin Division, Ambalamedu, Kochi.****Tender No:** 04030/2022-2023/E26472**Tender ID:** 2022 FACT 730274 1

S. No / Reference	SOR Tender Clause	Query	FACT Replies
4.01	SILO REPAIR,CIVIL,32647-12-PS- 004,SOW-4 Anchoring of shear connectors wherever required by using pure epoxy resin anchoring mortar with appropriate diameter of drilling of holes required for proper bonding into the concrete etc., complete, as per attached TPS 32647-12-PS-004.	Attached TPS 32647-12-PS-004 is missing. Also, we request to mention specific diameter for this item. Similar item is present in the tender where dia is mentioned (item no. 7.01)	TPS 32647-12-PS-004 is available from page 82 to 129 of the tender document PDF (tender_doc1) uploaded on etendering website. The shear connectors shall be 8mm dia with 10mm dia holes
BOQ item no. 6.01	SILO REPAIR,CIVIL,32647-12-PS- 004,SOW-6 Jacketing the existing column of size as shown in the drawing, as per attached TPS 32647-12-PS-004	Kindly specify grade of concrete to be used for this item	Grade of Concrete shall be M30
BOQ item no. 14.01	"Providing and laying, applying carbon fibre wrap at structural members as per attached TPS 32647-12-PS-004	Please specify the thickness of the wrapping system to be used/	The thickness of carbon fibre wrap shall be 300 GSM
General	All items in BOQ where it is mentioned as "ATTACHED TPS 32647-12-PS-004" The attachment is missing	Please provide the said attachment to understand the scope of work.	The TPS 32647-12-PS-004 is available from page 82 to 129 of the tender document PDF (tender_doc1) uploaded in e-tendering website. The documents with prefix numbering 32687 in the tender documents are part of the TPS 32647-12-PS-004